Headsets Direct, Inc.

Making Communication Easier

1470 W. Gurley St. • Prescott, AZ 86305

(800) 914-7996
(928) 777-9100
fax (928) 777-9120

Plantronics CS50 System Reset Instructions

HEADSET

⑭ Talk Button

⑯ Microphone Boom

⑮ Listen. Volume/MuteControl

⑰ Talk Indicator Light

Outside View

To recover from some fault conditions (refer to the Troubleshooting Section) you may need to perform a system reset.

To perform the system reset follow this procedure:

1. Press both the talk button ⑭ and the mute control ⑮ button on the headset for 5 seconds.

2. When the talk indicator light ⑰ on the headset blinks, release both buttons.

3. Press the talk button again.

4. Next reset the base unit by disconnecting the AC power adapter ㉔ from the AC power adpter jack ⑦ for 5 seconds, then reconnect.

The system reset operation is complete.

* The Telephone Configuration Dial will be set to #1 on the base for most phones.

Please call us at 1-800-914-7996 you have any questions or continue to have problems.